

FLAGG CREEK OUTFALL REHABILITATION – PHASE 1: 2021

OUTFALL BEFORE AND AFTER PHOTOS

THE VILLAGE OF WESTERN SPRINGS HAS COMPLETED PHASE 1 OF STORM SEWER OUTFALL IMPROVEMENTS ALONG FLAGG CREEK IN 2021. THE FIRST PHASE OF THE IMPROVEMENTS INCLUDED REHABILITATION ON OUTFALLS #31, #32 AND #33 LOCATED NEAR THE SOUTHERN END OF THE 2019 STUDY AREA NEAR THE RIDGEWOOD SUBDIVISION.

OUTFALL #31

BEFORE



AFTER



OUTFALL #32

BEFORE



AFTER



OUTFALL #33

BEFORE



AFTER

